From:
 Crawford, Beth

 To:
 Moore, Gary

 Subject:
 South Tank 3

Date: Wednesday, December 03, 2014 11:34:51 AM

Attachments: removed.txt

## Gary,

We had pH issues with the composite on South Tank 1/3/6. Can we have the Houston lab run a pH on the South Tank 3 just to confirm it really is as low as we think it is, 1.23?





## **Beth Crawford**

Scientist

Applied Science & Engineering

Federal Services

Direct: +1 419 429 5519 Fax: +1 419 425 6085

Beth.Crawford@CBIfederalservices.com

Please Note New Phone Number

CB&I

16380 U.S. Route 224 East Suite 100

Findlay, OH 45840

United States of America

www.CBI.com

This e-mail and any attached files may contain CB&I Federal Services LLC (or its affiliates) confidential and privileged information. This information is protected by law and/or agreements between CB&I Federal Services LLC (or its affiliates) and either you, your employer or any contract provider with which you or your employer are associated. If you are not an intended recipient, please contact the sender by reply e-mail and delete all copies of this e-mail; further, you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited.

This message contained an attachment which the administrator has caused to be removed.

\*\*\*\*\*\* ATTACHMENT REMOVED

Attachment name: [image001.jpg]
Attachment type: [image/jpeg]